

Summary of Faults Repaired by Software Upgrade

GD-01 / MD-01 / LM-02 / LM-03 / RB-01

How to display the firmware version installed in the audio:

1. Press SETUP button.
2. Tap GENERAL then ABOUT on the audios' LCD panel.

Ref.	Audio Mode	Fault Description	Fault Repaired Firmware ID
1	CD	Support for gapless CD track playback; the short silence between the end of an audio track and beginning of the next audio track is removed.	Firmware Version: V2.15T, Image Version: G1.56, Bluetooth Version: B113
2	Bluetooth	Clock time is refreshed correctly when Bluetooth screen is displayed.	
3	iPod™	Track information (ID3 tag, album art) does not update when selecting track FWD or REV. Affects devices using iOS 7.0 onwards.	
4	Bluetooth Phonebook	Issue affecting display of names entries greater than 20 characters is solved.	
5	Bluetooth Phonebook	Issue affecting display of multiple phone number entries is solved.	
6	Bluetooth	A previously paired phone will not automatically operate in hands-free mode through the car audio during a call where the car audio is switched on.	
7	Tuner	Buzzing/static sound when the audio is switched on in tuner mode.	
8	General	Audio set does not remain in user selected OFF condition after the vehicle ignition is cycled through ACC on and off.	
9	General	Erratic volume control when using steering wheel remote control.	